



# Release Note

## ICPAGING GATEWAY V1.5.1

<b>Document Name:</b>	Release Note		
<b>Document Date:</b>	31.Mar.2022		
<b>Document Revision:</b>	V1.00		
<b>Firmware name:</b>	ICPAGING GATEWAY V1.5.1		
<b>FW Release Date:</b>	31.Mar.2022		
<b>Package Names:</b>	update-core-image-barix-icpgw-1.5.1.tar (to be installed on M-400 device)		
<b>Yocto Layers Version Overview:</b>	<b>Layer</b> bitbake meta meta-multimedia meta-networking meta-python meta-oe meta-python2 meta-barix meta-barix-ipam400 meta-icpgw	<b>Branch</b> 1.46.0 master   master master oe-dunfell master develop	<b>Tag/Revision</b>  2246b0d7a71c69eb2e89c55991d1387069895466  c38d2a74f762a792046f3d3c377827b08aade513 6b3000729ce3424c2aa8a03cd46ef37b200d2fc1 51e3d10528ca10df15b847a8bb91e4780ee5fec3 9306baa6ffe55ce389a540a37e07001428f91fff b7af949834c14e3768b6a1215c14fc894d5d6a38

# 1 Hardware Compatibility

---

This firmware is fully supported on the following Barix devices:

- M400

**NOTE:** While this FW can run on other IPAM\_400 base devices from Barix, its complete functionality may not be guaranteed.

## 2 Fixed Bugs

---

The following bugs have been resolved compared to the previously released V1.5.0:

- The recorded message preview does not work on browsers installed on Mac or iOS

## 3 New Features and Improvements

---

The following new features have been implemented compared to the previously released V1.3.2vbeta:

- Up to 9 local audio files can be uploaded and be paged
- There is a new button created for each new file
- Prevent from paging and playing a file at the same time
- Button debouncing to prevent accidental multiple touches
- Record message feature with preview added
- 

## 4 Useful Tips and Known Issues

---

1. After performing a firmware update, the groups, users and audio files are reset to their default values
2. The last 3 recorded messages are temporary stored in memory for debugging purposes and can be found in /mnt/data/prerecorded\_messages/processed with the \*.rec extension. Upon reboot of the app those files are overwritten
3. When streaming to a IPAC device v2.8.0, the receiving device would hang. This is not present on ipac v2.7.3

# 5 Release generating details<sup>1</sup>

---

## 5.1 GIT release tag

Checkout the firmware-image-icpgw repo with the following tag:

v1.5.1

## 5.2 Compile commands:

Run the following command from the firmware-image-icpgw build folder:

```
bitbake -f core-image-barix-icpgw
```

# 6 Legal Information

---

© 2022 Barix AG, Zurich, Switzerland.

All rights reserved.

All information is subject to change without notice.

All mentioned trademarks belong to their respective owners and are used for reference only.

Barix and SIP OPUS CODEC are trademarks of Barix AG, Switzerland and are registered in certain countries.

For information about our devices and the latest version of this manual please visit [www.barix.com](http://www.barix.com)

Barix AG  
Limmatstrasse 21  
8005 Zürich  
SWITZERLAND

T +41 43 433 22 11  
F +41 44 274 28 49

[www.barix.com](http://www.barix.com)  
[sales@barix.com](mailto:sales@barix.com)  
[support@barix.com](mailto:support@barix.com)

<sup>1</sup> This information is intended for BARIX developers only